

Galaxy – High Technology s.r.o.  
NOTICE OF CORRECTIVE ACTION

**Service Bulletin**  
Galaxy Rescue System

GRS040709

---

ISSUED BY:

Galaxy High Technology s.r.o.

Tr 1. Maje 66/24a

460 01 Liberec 3

Czech Republic

Tel: +420 48-510 44 92

URL: <http://www.galaxysky.cz/>

DATE OF NOTICE: 7 April 2009

EFFECTIVE DATE: Immediately

AFFECTED SYSTEMS: Only those GRS LSA Systems listed by serial number below and shipped to the USA.

AFFECTED SERIAL NUMBERS: 3015-06-3149-3738; 3016-06-3150-3739, 3019-07-3155-3747, 3120-07-3266-3839, 3136-07-3273-3865, 3135-07-3272-3856, 3266-07-3407-3981, 3265-07-3406-3980, 3326-07-3476-4050.

NOTICE ID: GRS040709 (replaces GRS040609)

DISCUSSION: Quality control reports regarding fuel manufactured by a supplier for the solid rocket used in one batch of Galaxy parachute activation systems *cannot confirm* that the fuel meets standards.

Due to the importance of the reliability of the rocket system, the Galaxy firm has issued this notice for replacement of the rocket in those systems indentified by the specific system serial number above.

CORRECTIVE ACTION: Replace and inspect the rocket system serial numbers installed in the affected aircraft in accordance with this Galaxy Bulletin GRS040709. Document this action in the aircraft maintenance records.

COSTS: Galaxy will provide labor and materials for rocket replacement of affected aircraft systems. System must be presented at owner's expense within one year from the date of this notice (30 April 2010) at a Galaxy designated service location. Replacement after that date will be at cost and quoted individually to the Owner.

END GRS040709